

Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

ENGINEERING CHANGE REQUEST

Tel (613) 632-5200

Fax 613 632-5246 **ECR 195** 4/9/21 11:45 AM Date Opened: Requested By: Clarke, Jeffery Responsible Engineer: Clarke, Jeffery Type: Drawing/Pattern Change Priority: Medium Requester*: Clarke, Jeffery Status: **Under Review** DE Approver*: Provencal, Chris Reason: Assembly of the step requires application of ECR Lead*: Drouin, Steven sealant before powder coating. To ensure **ECR Specialist:** Drouin, Steven performance of the sealant following powder coating, the sealant is changed to a high-temp Dow Corning 736. Expense: Target Date: **Execution Date: ECR Approval No:** RE (R&D): **BRIEF D5812 Step - Sealant Change **DESCRIPTION**:** Status Note: DESCRIPTION/ ADR Change sealant from PR-1422, P/S 890, Sikaflex-CONTENT**: 241/-291, or MIL-S-8802 specified on drawing to Dow Corning 736. **CUSTOMER APPROVALS** Customer **Customer Visible Customer Approval Required Customer Approved PARTS** Dart

Part No	Rev	Status	Name	Туре	Customer Part	Special Comments	Documents
D350-1082-		Active	Short Cabin Step	Finished	D350-1082-011		
011			Installation	Good	D350-1082-011		
					D350-1082-011		
					D350-1082-011		
					D350-1082-011		
					D350-1082-011		

					D350-1082-011
D5812-041	Oi	n hold	Short Step Assembly	Finished Good	

	ITODY	DIODO	COLTICAL
INVE	VIORY	DISPO	SITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty		Qty Scheduled for Production
D350-1082-011		0 Quarantine	0 *	0	Update Jobs only when drawing approved
D5812-041		1 Quarantine	0 *	0	Update Jobs only when drawing approved

ACCOUNTING JOBS

Accounting Job No	Туре	Group	Status
SE CAD 1082	Sustain Engineering		Active

Ε	F	F	Ε	С	T	S
			_	v	•	U

Effect Group	Effects		
ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (D5812 Rev. A), Update/Create MDL (MDL-D350-1082)		
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review		
4. Production Type	In-house production		
5A. ECR Lead Assessment - MINOR Changes	Minor change to component to improve fit or manufa (D5812 - Change sealant to Dow Corning 736)		
6A. Production Impact	Update/Create BOMs & Routes (Sealant to be applied before powder coating. Update sealant per revised drawing.)		